

Winter work has started early with this clearance work along the footpath between Hydehurst Lane and Fleming Way.

Public/cyclists are now able to access this footpath without any obstacles in the way.



MANOR RO

BUSINESS DISTRIC CRAWLEY & GATWIC Here are the before photo of a large task we took on in Tinsley Lane North, clearing a very overgrown and neglected footpath.











With the support from our small works team we able to use a machine called an Avant to help clear the footpath.

The detritus that was cleared from here was reused to create a bunding along the side of this footpath to help prevent weed growth, which will be easier to maintain.

With a very satisfying end result, it turns out this area is actually the old Gatwick Road.









Location: Tinsley Lane North









We experienced some vandalism within The Terrace where screws and wood were removed from seats. These have now been repair by our team.







During the summer we came across these self seeded shrubs which had forced their way through the pathway, leaving very dangerous trip hazards.

WSCC were contacted and have since been out to remove the growth and repair the footpath, leaving this area now safe to the public.





Location: Gatwick Road

