



Hedge cutting along Woolborough Lane cycle path to clear blind spots for cyclists. Also weed clearing to prevent encroachment onto the footpath.


[www.manorroyal.org/maintenance](http://www.manorroyal.org/maintenance)






We are clearing Pocket Parks daily to prevent any slips or trips.

Location – Priestley Way.




Grass verges have also been edged around Pocket Parks. Waste grass that has been cut off has been used to reinstate other damaged verges.






These photos are before the work was carried out to replenish the woodland path in Crawter's Brook.





During photos - The steps we took during this replenishment was to cutback all overhanging brambles to widen the footpath, with then support from our inhouse tractor team to deliver the woodchips to site.





After photos – around 15 tons of woodchips were used to replenish this footpath.

[www.manorroyal.org/maintenance](http://www.manorroyal.org/maintenance)