



**MANOR ROYAL**  
BUSINESS DISTRICT  
CRAWLEY & GATWICK

Manor Royal Maintenance Team  
November 2023 Picture Report

These areas will be checked and cleared on a regular basis to prevent this building up again.



Detritus build up has been removed.



Location – Gatwick Road.





Many high footfall areas have been blown to prevent any slips or trips.



Location – Gatwick Road.



Location – Magpie Walk.

High footfall areas are being checked and cleared weekly.





Larger volumes of leaf fall are being removed from grass areas.



We do this as leaves will starve the grass of much needed light and air, which will prevent the grass from growing.

However, in some area's leaves will be left to support wildlife and soil health.



Location – Manor Royal Road.



Areas where which have a higher build-up of leaves are being cleared to keep footpaths clear.



Location – Manor Royal Road.







Location – Woolborough Lane  
Cycle Path.

Cycle/footpaths are cleared of leaves  
and detritus to allow for clear access.



[www.manorroyal.org/maintenance](http://www.manorroyal.org/maintenance)