



**Manor Royal Maintenance Team:
September Picture Report**



We have then reinstated the verges using the turf that was cut off.



Our team has been out edging grass verges.





**Manor Royal Maintenance Team:
September Picture Report**



Our team are looking to clear all traffic islands to prevent weeds from growing.



Detritus has been clearing on various traffic islands throughout Manor Royal.

Location – Gateway
2, Manor Royal Road.




We continue to clear
debris from
roundabouts and
traffic islands.



Manor Royal Maintenance Team:
September Picture Report

Location – Gateway
5, Gatwick Road.



Location – Gateway 4, James Watt Way.



Grass verges have been edged and off cuts have again been used to reinstate damaged areas of grass.



www.manorroyal.org/maintenance